



HAZARDOUS MATERIAL SPILLS INFORMATION REQUEST

GLOBAL CHURCH ST PORT (MOBIL)
50 CHURCH ST

ALBANY, NY NO ZIP PROVIDED

Spill Number: 1504084

Close Date:

ADDRESS CHANGE INFORMATION

Revised street: NO CHANGE
Revised zip code: 12202

Source of Spill: COMMERCIAL/INDUSTRIAL
Notifier Type: Other
Caller Name:
DEC Investigator: BXBROWN

Spiller: GLOBAL (MOBIL)
Notifier Name:
Caller Agency:
Contact for more spill info: COLEMAN

Spiller Phone:
Notifier Phone:
Caller Phone:
Contact Person Phone:

Category: Known or probable release, where, without action, there is a potential for a fire/explosion hazard (indoors or outdoors), contamination of drinking water supplies, or significant release to surface waters.

Class: Willing RP – DEC Field Response – Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards		Penalty Recommended	
07/16/2015		EQUIPMENT FAILURE	NO		NO	
Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	0.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

oil water mix leaked to soil from underground pipeline/clean up and repairs underway/clean harbor on site

DEC Investigator Remarks:

8/19 – Add this to the list of sites that have lost out notes.

So to recap –

Global noticed fuel coming up thorough the pavement near the SPCC tank. The tank and piping were eventually uncovered, and it was discovered that a fitting had broken in the subsurface. As a truck was unloading in to the SPCC tank, it was leaking out the fitting. Based on the visual inspection and odors of the soil, it appears that this has been leaking for some time. A small amount of contamination was removed and Global is preparing to install wells to determine the levels and extent of the contamination. A diagram of the system and how those tanks function is in DDoc.

10/20 – MF left msg for Matt Root, Envirospec, regarding report. 265–4533

11/13 – Exchange with Envirospec. Suggested that they do vac truck extractions on wells and additional sampling. See Ddoc for info.

5/2/16 – **Alas, another spill where the notes have gone missing.** To recap, Global removed some soil in the area and placed wells near the tank. DEC has received and approved their plan for additional investigation. Currently awaiting report.

5/31/16 – Note from Roux

..Matt,

We are scheduled to complete this well installation between June 7–8, 2016. Please let me know if you have any questions.

Thanks, Katie..

6/13 – MF spoke to Katie @ Roux. No new wells were installed during most recent drilling event due to various refusals. Katie has asked that this site be monitored and then incorporated into the entire long term site. I advised her that we will need some short term monitoring of the site and a map that shows the existing active wells in the area. I also advised that if product continues to show up in the wells, active remediation would be required. She is going to gather up the well data and supply it to me.

1/31/17 – FOIL W016097–122116, selected EDOCS from 9214481, 9214484, 1110257, 1504084 via WebQA.

2/27/17 – FOIL W017339–012617, EDOCS VIA FTS w/9011772, 1605027, 1604870, 1504084, 8910698