



## HAZARDOUS MATERIAL SPILLS INFORMATION REQUEST

**AUGUSTINE'S & SON EXXON**

300 LYONS ROAD

GENEVA, NY 14456

Spill Number: 8302434

**Close Date:**

ADDRESS CHANGE INFORMATION

Revised street: NO CHANGE

Revised zip code: NO CHANGE

Source of Spill: UNKNOWN

Notifier Type: Other

Caller Name:

DEC Investigator: JRMARCHI

Spiller:

Notifier Name:

Caller Agency:

Contact for more spill info:

Spiller Phone:

Notifier Phone:

Caller Phone:

Contact Person Phone:

Category: Known release which created a fire/explosion hazards (inside or outdoors), drinking water supply contamination, or significant releases to surface waters.

Class: Willing RP – DEC Field Response – Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards		Penalty Recommended	
02/27/1984		UNKNOWN	NO		NO	
Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
GASOLINE	PETROLEUM	3000	GALLONS	0	GALLONS	GROUNDWATER

Caller Remarks: NO REMARKS GIVEN FOR THIS SPILL

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead\_DEC Field was JM

// : CB(ACTIVE) 86-05-06 RECOVERY WELL 12 DIA. INSTALLED 85-12-09. USING OLD RECOVERY SYSTEM & RECOVERING 45 GALS PER WK. MONITORING PROGRESS.

// : EXXON CO. PAYING FOR CLEANUP.

// : CH INSPECTED 7/24/87. ONE MONITORING WELL SHOWED 8 OF PRODUCT. WELL IS THE CLOSEST ONE TO THE NORTH OF RECOVERY WELL. ALL OTHER WELLS CLEAN.

// : JM INSPECTED IN EARLY SEPT. MONITORING WELLS WERE CLEAN AND THERE WAS APPROX. 2 PRODUCT IN RECOVERY WELL.

// : CH INSPECTS 12/17/87 RECOVERY WELL SHOWS 0 2 OTHER WELLS IN BLDG. HAVE 8& 2 .WELL IN FRONT OF GARAGE DOOR HAD 4 .ALL OTHER WELLS SNOWED IN.

08/18/88: EXXON FEELS REG.TANK IS LEAKING ASK FOR TEST.L&O MECH. DOES TEST 8/11/88 BY JIM BUMPUS.EXXON CONSULTANT ON SITE.TEST INTERRUPTED 5 MIN. BEFORE END.THEY FEEL IT WAS A GOOD TEST.

08/18/88: 8/11/88 NO PRODUCT IN ANY OF THE WELLS.WILL CHECK AFTER ONE MORE FLUCTUATION OF GROUND WATER.IF NOTHING SHOWS WE CAN CLOSE OUT AND STOP RECOVERY.

04/13/89: 04/13/89 CB, PM AND BF INSPECT SITE, AND BAIL WELLS. WELL TO SOUTH NEAR ISLAND HAS 4 OF DARK PRODUCT. 2 WELLS NEAR RECOVERY WELL HAVE PRODUCT. 1 TO N HAS 5 1/2 OF CLEAR PRODUCT.

04/13/89: 04/13/89 ONE TO THE SOUTH NEAR RECOVERY WELL HAS 10 OF CLEAR PRODUCT. WELL TO THE NORTH IN FRONT OF GARAGE DOORS HAS 9 1/2 OF PRODUCT A LITTLE DARKER THAN PRODUCT NEAR RECOVERY WELL.

04/14/89: 04/14/89 CH ATTEMPTS TO CALL FRED ANDERSON OF EXXON, 716-656-7748 TO REINSTATE RECOVERY PROCESS. HE IS NOT IN, ASK FOR RETURN CALL.

07/18/89: 07/18/89 CH INSPECTS. WELLS 1 TO THE SOUTH OF BURIED TANKS HAS NO PRODUCT. WELL 2 IN FRONT OF GARAGE DOOR HAS ~1/8 PRODUCT. WELL 9 IN RECOVERY SHED TO SOUTH HAS 1/8 PRODUCT.

07/18/89: 07/18/89 #10 JUST TO NORTH OF #9 HAS ~1/4 . MR AUGUSTINE SAYS THAT IN LAST 203 WEEKS, THEY HAVE NOT BEEN GETTING ANY PRODUCT. DURING JUNE, MOST THEY GOT WAS 1-2 MAX.

07/18/89: 07/18/89 DURING MAY IT WAS 4-5 . WATER TABLE SEEMS TO BE DOWN, BUT DID NOT HAVE SONIC INTERFACE TO USE FOR WATER LEVELS.

09/25/89: 09/25/89 SPOKE W/ MR.AUGUSTINE @ BEGINNING OF SEPT.HE HAS BEEN CHECKING WELLS & NO PRODUCT IS BEING FOUND.HE ALSO WANTS TO HAVE RECOVERY SYSTEM PULLED.

09/25/89: 09/25/89 CH SPEAKS TO FRED ANDERSON OF EXXON ABOUT REMOVING SYSTEM AND THE RECOVERY SHED. HE SAYS HE WILL HAVE IT DONE.

09/26/12 FILE REVIEW UPDATE: CERTIFIED ENVIRONMENTAL SERVICES (CES) COLLECTED SOIL SAMPLES DURING TANK CLOSURE REMOVAL WORK PERFORMED JAN. 1999. THREE 4000 GALLON GASOLINE UST'S REMOVED, AND BASED ON IMPACTS NOTED, SPILL WAS REPORTED (SPILL # 9812255). PID READINGS TAKEN BY CES RANGED FROM 75 - 2000 PLUS PPM. CONFIRMATORY SOIL SAMPLE RESULTS ON ALL SIDEWALLS AS WELL AS BOTTOM OF EXCAVATION INDICATED EXCEEDANCES FOR SOIL CLEANUP GUIDANCE NUMBERS.

01/06/2016 PM SPILL REVIEW, GES RETAINED BY EXXONMOBIL. SAMPLED WELLS, INSTALLED ADDITIONAL WELLS. REPORT TO BE SUBMITTED.