



HAZARDOUS MATERIAL SPILLS INFORMATION REQUEST

HORNELL CITY WELLS
 [REDACTED] SENECA RD NORTH

HORNELLSVILLE, NY NO ZIP PROVIDED

Spill Number: [REDACTED]

Close Date: 11/18/2009

ADDRESS CHANGE INFORMATION
 Revised street: [REDACTED] N SENECA RD
 Revised zip code: NO CHANGE

Source of Spill: UNKNOWN
 DEC Investigator: pclinden

Spiller: UNKNOWN
 Contact for more spill info: TOM KLASEUS (NYSDOH)

Spiller Phone:
 Contact Person Phone: (607) 324-8371

Category: Known release which created a fire/explosion hazards (inside or outdoors), drinking water supply contamination, or significant releases to surface waters.
 Class: Unknown RP – DEC Field Response – DEC Corrective Action Required

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards		Penalty Recommended	
11/12/2008	11/18/2009	UNKNOWN	NO		NO	
Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
TRICHLOROETHENE (TCE)	HAZARDOUS MATERIAL	0.00		0.00		GROUNDWATER DRINKING WATER

Caller Remarks:

WHILE DETERMINING LOCATION OF CITY WELLS IN RELATION TO ACTIVE SPILLS, LINDENFELSER LEARNED FROM TOM KLASEUS THAT VOCs HAD SHOWN UP IN SOME ANALYSES OF THIS SUPPLEMENTARY WATER SUPPLY LOCATED IN THE MIDDLE OF A WETLAND BETWEEN SENECA RD AND RT. 36.

DEC Investigator Remarks:

THE TWIN WELLS ARE LOCATED 42 DEG 21' 33 NORTH LATT BY 77 DEG 39' 57 WEST LONG., AND ARE ACCESSIBLE BY GATED SERVICE ROAD BEHIND AND BETWEEN THE COUNTRY KITCHEN RESTAURANT AND MONRO MUFFLER.

RECEIPT OF FOUR SEPARATE ANALYSES BEGINNING IN 2007 HAS SHOWN THAT ONLY TCE HAS APPEARED, AND EXCEEDED DRINKING WATER STANDARDS ONCE: 5.5 PPB (USGS SAMPLING 11/12/08). BECAUSE IT IS A NON-PETROLEUM CHEMICAL, THE CASE IS BEING REFERRED TO DIV. HAZ. WASTE REMEDIATION FOR FOLLOWUP. NO FURTHER ACTION BY SPILLS IS NECESSARY.

11/18/09 FORWARDED TO ENVIRONMENTAL REMEDIATION. PAPER FILE REMOVED PER FILE RETENTION POLICY.