



HAZARDOUS MATERIAL SPILLS INFORMATION REQUEST

FORMER WENDY'S
840 ARSENAL STREET

WATERTOWN, NY NO ZIP PROVIDED

Spill Number: 1000756

Close Date:

ADDRESS CHANGE INFORMATION

Revised street: NO CHANGE
Revised zip code: 13601

Source of Spill: GASOLINE STATION OR PBS FACILITY
Notifier Type: Other
Caller Name:
DEC Investigator: jlrogers

Spiller: unk
Notifier Name:
Caller Agency:
Contact for more spill info: JASON PRESTON

Spiller Phone:
Notifier Phone:
Caller Phone:
Contact Person Phone: (315) 788-3900

Category: Known or probable release, where, without action, there is a potential for a fire/explosion hazard (indoors or outdoors), contamination of drinking water supplies, or significant release to surface waters.
Class: Willing RP – No DEC Field Response – Corrective Action Initiated or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards		Penalty Recommended	
04/19/2010		UNKNOWN	NO			
Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
GASOLINE	PETROLEUM	0.00	UNKNOWN	0.00	UNKNOWN	SOIL, GROUNDWATER

Caller Remarks:

ON SITE OF FORMER WENDY'S WHICH WAS FORMERLY A GAS STATION. DOING PHASE II BORINGS; FOUND 350 PID IN WET SANDY SOILS; HEAVY STAINING; CLEAN UP IS PENDING; CALLER BELIEVES WATER IS AFFECTED

DEC Investigator Remarks:

4/20/10: Spoke to Bill Plante, Gympo, PC. in 1960 – 1970 this location was a gas station owned by the Mara Family. Gympo is working for the church delineating the plume. Gympo has photos from 1966 that show the tank field and pump islands. At that time Arsenal St was 2 lanes. Hence the pump island contamination is believed to extend under the side walk and under the existing roadway. Dark soils were encountered at 16 fbg. Readings of 1800 ppm were recorded on the PID in the area of the pump island. A substantial amount of contamination is believed to go into the ROW. Mr. Plante to forward via email the property owner information.(jlr)

5/24/10: Kelly Buchler, Delta Consultants, Baltimore, MD represents the owner. GPR done March 3, 2010; no tanks found. Complete Phase II to be done. Owner waiting for our RP letter. Delta to send Department contact info for owner and delta.(jlr)

Copyright 2017 Toxics Targeting, Inc. April 17, 2017

Kelly R. Buchler – Project Professional – North American Operations Delta Consultants, an Oranjewoud N.V. Company Direct +1 410 309 4360 – Mobile +1 612 703 6826 – USA Toll Free 800 477 7411 kbuchler@deltaenv.com – www.deltaenv.com

8/30/10 received SSI report. shallow contamination was found near arsenal street in the area of the former pump island. GW, 12–14.7 fbg, across the entire site is contaminated with a band of contaminated soil 14–16 fbg. Report provides an extensive history of site ownership. (jlr)

2/17/14: rec'd Supplemental Subsurface Inves Report prepared by GES on behalf of ExxonMobil. This report does not mention or acknowledge the apparent source material (former pump island) in the SE corner of the property and there are no SBs or MWs in that area or proposed for that area.(jlr)

2/21/14: TC with Bill Hackett. Discussed the above. Mr Hackett insisted that GES was not ignoring the source area and that they were collecting more data to determine proper remedial actions. Mr Hackett said they would remediate the area in the SE corner (former pump Island). I suggested this be done through excavation with trench boxes.

3/17/14: Called GES, Patricia Domago. Requested contact infor for Laurie McCarthy, ExxonMobil Env Services. (jlr)

Laurie M. McCarthy

ExxonMobil Environmental Services Company New York Retail Project Manager 38 Varick Street Brooklyn, New York 11222 Office: 718–404–0679 Fax: 718–404–0681 Cell: 207.299.4660 Email: laurie.m.mccarthy@exxonmobil.com

10/17/14: TC with Mr. Stereno, adjacent prop owner. Borings were done on his property last week. Discussed the project and accessibility to records. (jlr)

10/28/14: rec'd 3rd qtr GW monitoring report. Off site investigation was done. Separate report to be sent in.(jlr)

12/22/14: rec'd SSIR dated 12/19/14. A remedial plan will follow in the first half of 2015, prob insitu remediation. (jlr)

4/27/15: rec'd site monitoring report. A remedial plan will follow in the first half of 2015. (jlr)