



HAZARDOUS MATERIAL SPILLS INFORMATION REQUEST

MOBIL S/S # 06-909

114 SOUTH GREELEY AVE

CHAPPAQUA, NY NO ZIP PROVIDED

Spill Number: 8900072

Close Date:

ADDRESS CHANGE INFORMATION

Revised street: 214 SOUTH GREELEY AVE

Revised zip code: 10514

Source of Spill: GASOLINE STATION OR PBS FACILITY

Notifier Type: Responsible Party

Caller Name: MARK LEACH

DEC Investigator: MXTIPPLE

Spiller: MOBIL OIL CORP

Notifier Name:

Caller Agency: MOBIL OIL CORP

Contact for more spill info:

Spiller Phone:

Notifier Phone:

Caller Phone: (703) 849-5384

Contact Person Phone:

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.

Class: Willing RP – DEC Field Response – Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

| Spill Date | Date Cleanup Ceased | Cause of Spill | Meets Cleanup Standards | | Penalty Recommended | |
|------------|---------------------|----------------|-------------------------|--|---------------------|--|
| 04/03/1989 | | UNKNOWN | NO | | NO | |

| Material Spilled | Material Class | Quantity Spilled | Units | Quantity Recovered | Units | Resource(s) Affected |
|------------------|----------------|------------------|---------|--------------------|---------|----------------------|
| GASOLINE | PETROLEUM | 0.00 | GALLONS | 312.00 | GALLONS | GROUNDWATER |

TANK TEST INFORMATION

| Tank Number | Tank Size | Tank Test Method | Leak Rate | Gross Leak or Failure |
|-------------|-----------|------------------|-----------|-----------------------|
| | 0 | Unknown | 0.00 | UNKNOWN |

Caller Remarks:

AIR STRIPPER PUMP AND TREAT, STORM DRAIN DISCHARGE

DEC Investigator Remarks:

05/03/2001 LETTER SENT TO EXXONMOBIL BY J. HARDY; ALL WELLS MUST BE SAMPLED THIS QUARTER. **EXTENT OF SOIL CONTAMINATION IN VICINITY OF MW10 MUST BE DEFINED.** PROPOSAL FOR WORK DUE BY 6/15/2001.

3/19/09 Based upon Meeting with Exxon/Mobil/Ges will submit Historical Data for review. JO'M

2/14/11 Review indicates no statistically significant changes. JO'M

6-24-13 request FIR RDB 07-25-14 call from Apache, inquiring about recent activity on the spillcase by GES RDB PJD sent letter to GES in May 2014

12-14, Mobil just back sampling after 10 year hiatus with new spill One well, MW-10, severely impacted(product through much of the 2000s) PJD

4-7-15 met with GES and EOM; MT to review data, RDB

9/23/15 QMR reviewed in D2, MW-10 still significant BTEX, e-mailed reply regarding future active effort to address MW-10. mt

2/22/16 changed lead from Bendel to Tipple. mt 2-25-16 Met with GES and Exxon Mobile to discuss site. GES contends that existing spill is new. PProvided New Fields report on specialized ethanol analytical method. It showed ethanol signature not seen in historical 8260 sample results. ghp

3/21/16 Reviewed QMR from Ges for spill #89-00072, filed in D2,(same location as 1507420) describing the detection of ethanol at 160,000 ug/L in the groundwater sample collected from MW-10. Spoke with Denise Heinzinger from WCDOH, Sent do work letter for Spill #1507420 to Preferred Auto Alex Fernandez with a cc to Apache Oil Christopher Ohl. mt