



HAZARDOUS MATERIAL SPILLS INFORMATION REQUEST

I/O FORMER MOBIL TERMINAL

BAY STREET/BURKE

SAG HARBOR, NY NO ZIP PROVIDED

Spill Number: 1000277

Close Date: 04/20/2012

ADDRESS CHANGE INFORMATION

Revised street: NO CHANGE

Revised zip code: 11963

Source of Spill: UNKNOWN

Notifier Type: Citizen

Caller Name:

DEC Investigator: NJACAMPO

Spiller: EXXON/MOBIL

Notifier Name:

Caller Agency:

Contact for more spill info: TIM CULVER

Spiller Phone:

Notifier Phone:

Caller Phone:

Contact Person Phone: (631) 725-4100

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.

Class: Willing RP – DEC Field Response – Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards		Penalty Recommended	
04/07/2010		UNKNOWN	NO		NO	
Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	0.00	GALLONS	0.00	GALLONS	SOIL

Caller Remarks:

Caller reports oil seeping up thru the asphalt and onto the road surface/best location is Bay St by the Break Water Yacht Club and the boat yard. Culver states that there use to be an old tank farm in this area. Call Culver for additional details

DEC Investigator Remarks:

4/7/2010 t/c to Tim Culver, No Answer

Brian D. to check 4/8/2010

4/8/2010 12:36 Brian D. On site

Dan Grapski, ExxonMobil on site Noelle Clarke, Roux Associates on Site

Upon Inspection Found

–Area is located on the North side of Bay Street at the intersection of Bay and Burke. –Dan has a cleanup crew on site with a vac truck and absorbents.

–Area of the asphalt pavement is heaving. When stepped on, oil/ petroleum seeps out of the asphalt.

–The petroleum is dark black in color and has a gasoline like odor.

–Water/ puddle has been recovered from the roadway and they are placing absorbents on the seepage within the street. –There are 2 wells in the roadway on Bay St.

–Per Dan the well has a heavy sheen and some “black” petroleum product. The wells have been pumped out.

–It appears that groundwater is just below the roadway. Puddling can be seen on the well covers.

–Property on the north side of Bay street is under construction. Two pits have been dug to groundwater adjacent to the roadway.

–No floating product/ sheen/ petroleum odors in the soil or groundwater.

Per Dan, ExxonMobil will continue to clean up the oil seeping through the roadway until they can look through their records from the old tank farm.

12:56 Off site 4/9/10 15:15 ACAMPORA HAD TELECON WITH DAN GRAPSKI AT EXXON/MOBIL WILL CONTINUE INTERIUM REMEDIAL MEASURES AND WILL CONTACT VILLAGE TO ISOLATE SUBJECT ROADWAY. EXXON/MOBIL ATTEMPTING TO LOCATE FILES ASSOCIATED WITH SITE INCLUDING CONDITIONS OF SALE AND LIABILITY -----

04/16/2010 @ 13:43: Acampora had telecon with Dan Grabski at ExxonMobil. Roux continues to monitor site conditions. However, seepage appears to have stopped. Groundwater table has dropped and water/petroleum has also stopped seeping out of roadbase and wells. ExxonMobil continues to review records regarding responsibility/liability. They will re-evaluate next week and advise.

4/19/2010 13:12 Brian D. On Site

–Groundwater has subsided. No Additional oil seeping from the asphalt roadway. –Water is down approx 2 bg within the Wells. Minor sheen observed on the water within the wells. –Minor staining on the roadway, speedy-dry is still in place in some areas. –Asphalt is soft in the areas the oil seeped through it.

13:08 Off site

12/24/10 FILE REASSIGNED