



HAZARDOUS MATERIAL SPILLS INFORMATION REQUEST

WILLIAM'S MOBIL
RT 12

ALEXANDRIA BAY, NY 13607

Spill Number: 9102649

Close Date:

ADDRESS CHANGE INFORMATION

Revised street: STATE HWY 12

Revised zip code: NO CHANGE

Source of Spill: GASOLINE STATION OR PBS FACILITY

Notifier Type: Tank Tester

Caller Name: KEN NETTO

DEC Investigator: UNASSIGNED

Spiller: ROBERT WILLIAM'S

Notifier Name:

Caller Agency: DEC

Contact for more spill info:

Spiller Phone: (315) 482-2822

Notifier Phone:

Caller Phone: (315) 785-2513

Contact Person Phone:

Category: Known petroleum or hazardous material release with minimal potential for fire/explosion (indoors or outdoors), drinking water contamination, or releases to surface waters.

Class: Willing RP – DEC Field Response – Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards		Penalty Recommended	
06/05/1991		OTHER	NO		NO	

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
GASOLINE	PETROLEUM	0.00	GALLONS	0.00	GALLONS	GROUNDWATER
MTBE (METHYL-TERT-BUTYL ETHER)	HAZARDOUS MATERIAL	0.00	UNKNOWN	0.00	UNKNOWN	

TANK TEST INFORMATION

Tank Number	Tank Size	Tank Test Method	Leak Rate	Gross Leak or Failure
001	0	Unknown	0.00	UNKNOWN
002	0	Unknown	0.00	UNKNOWN
003	0	Unknown	0.00	UNKNOWN

Caller Remarks:

CONTAMINATED SOIL FOUND DURING TANK REMOVAL. GW INVESTIGATION REQUIRED.

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead DEC Field was DER,W,G 10/04/91: THREE WELLS HAVE BEEN INSTALLED AND SAMPLED. **PETROLEUM ODORS OBSERVED IN THE WELLS** BY K.NETTO.

07/26/93: SENT TAKEOVER LETTER TO MR. WILLIAMS DATED 7/26/93. (KG).

02/02/2002 BJ REVIEWED FILE. **GW** SHOWS A SIGNIFICANT PLUME ON SITE. PLUME BOUNDARIES NOT DEFINED. GROUNDWATER FLOW IS INCONCLUSIVE. **POTENTIAL IMPACT TO NEARBY WETLAND AREA THROUGH STORM SEWER.** ADDITIONAL INVESTIGATION TO DETERMINE GROUNDWATER FLOW DIRECTION, PLUME BOUNDARIES AND PREFERENTIAL MIGRATION PATHWAYS IS NEEDED. LAST LETTER FROM KG IN 92 STATING WHAT NEEDED TO BE DONE NEXT. **NO RESPONSE.**

NYSDEC FALL 1998 MTBE SURVEY INFORMATION FOR 9102649

Maximum MTBE concentration: 42020.0 PPB
BTEX offsite: No

Current MTBE concentration: 42020.0 PPB

Source of MTBE

Steel Underground Storage Tank - X
Fiberglass Underground Tank -
Aboveground Storage Tank -
Piping - X
Source not identified -
Other source -

Number of private drinking water wells impacted: 0
Number of public water supply wells impacted: 0
Number of private drinking water wells impacted: 0
Number of replacement wells drilled: 0
Number of water main extensions: 0
Number of water main hookups: 0
Number of residences provided w/ bottled water: 0
Number of people affected: 0

Indoor Air Impacts : No
Aquifer Impacts : No

Ongoing remediation: No

Monitoring Frequency

Monthly - Quarterly - Semi-annual - Annual - Other -

Remedial Action used

No Action -

Groundwater

Pump and Treat -
Air sparging -
Bioreactor -
Natural attenuation -
Oxygen injection -
Biosparging -
Dual phase extraction -
Other -

Soil

Soil Vapor extraction -
Excavation and disposal -
Bioremediation -
Low temp thermal desorption -
Oxygen injection -
Other -

Under investigation: Yes

Dept. of Health involvement: No

Dept. of Health Remarks: No remarks given for this spill

General Remarks: No remarks given for this spill