



## HAZARDOUS MATERIAL SPILLS INFORMATION REQUEST

### FAIR OAKS EXXON

280 BLOOMINGBERG ROAD

WALLKILL, NY NO ZIP PROVIDED

Spill Number: 0608472

Close Date:

#### ADDRESS CHANGE INFORMATION

Revised street: 280 BLOOMINGBURG RD

Revised zip code: 10940

Source of Spill: GASOLINE STATION OR PBS FACILITY

Notifier Type: Other

Caller Name:

DEC Investigator: kabrowne

Spiller: EPP FAIROAKES LLC – FAIROAKES EXXON

Notifier Name:

Caller Agency:

Contact for more spill info: STEVE KALKA

Spiller Phone:

Notifier Phone:

Caller Phone:

Contact Person Phone: (845) 434-3509

Category: Known or probable release, where, without action, there is a potential for a fire/explosion hazard (indoors or outdoors), contamination of drinking water supplies, or significant release to surface waters.

Class: Willing RP – DEC Field Response – Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards		Penalty Recommended	
10/24/2006		OTHER	NO		NO	
Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	0.00	GALLONS	0.00	GALLONS	SOIL

#### Caller Remarks:

PBS No: 3-601210 exploratory digging and found 200 tons of contaminated soil and is stock piled: doloros is on site from dec

#### DEC Investigator Remarks:

D. WEHRFRITZ DEC ON SCENE. WEATHERED GASOLINE CONTAMINATED SOIL IS BEING REMOVED.

12/7/15 – The gasoline station went through several owners and remedial work fell behind. The current owner request closure. The DEC did not received enough information to determine closure. The DEC requested current groundwater sampling data. The site owner provided sampling data from the on site potable well; which show non detect for petroleum. A site visit was conducted to show the site owner the five monitoring wells that needed to be sampled. The site owner was advised to hire a consultant or sampling technician to collect groundwater samples. The samples are to be analyzed for VOCs and SVOCs by a NYSDOH certified laboratory. And the sampling results be submitted to the DEC while a decision will be made on the site to either continue monitor/remediate or close the spill. KAB

1/28/16 – Sampling results submitted to the DEC. After more that a decade there is still significant petroleum contamination in monitoring well MW-4. Both the consultant and the current owner were told that area around the MW-4 needed to be remediated. The previous owner proposed excavating around MW-4. It was suggested that excavation would still be an acceptable proposal. KAB