



HAZARDOUS MATERIAL SPILLS INFORMATION REQUEST

EXXON S/S

1085 NORTHERN BLVD

FLOWER HILL/ROSLYN, NY NO ZIP PROVIDED

Spill Number: 9510367

Close Date:

ADDRESS CHANGE INFORMATION

Revised street: NO CHANGE

Revised zip code: 11576

Source of Spill: GASOLINE STATION OR PBS FACILITY

Spiller: EXXON COMPANY,USA

Spiller Phone:

Notifier Type: DEC

Notifier Name:

Notifier Phone:

Caller Name: ROBERT DECANDIA

Caller Agency: NYSDEC

Caller Phone: (516) 444-0320

DEC Investigator: RDDECAND

Contact for more spill info:

Contact Person Phone:

Category: Known or probable release, where, without action, there is a potential for a fire/explosion hazard (indoors or outdoors), contamination of drinking water supplies, or significant release to surface waters.

Class: Willing RP - DEC Field Response - Corrective Action Initiated, Taken Over, or Completed by RP or Other Agency

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards		Penalty Recommended	
11/09/1995		UNKNOWN	NO		NO	

Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
GASOLINE	PETROLEUM	0.00	GALLONS	0.00	GALLONS	SOIL
MTBE (METHYL-TERT-BUTYL ETHER)	HAZARDOUS MATERIAL	0.00	UNKNOWN	0.00	UNKNOWN	SOIL

Caller Remarks:

GAS CONTAMINATED SOIL ENCOUNTERED DURING A STATION RE-BUILD - APPROX 600 CUBIC YARDS OF CONTAMINATED SOIL WAS REMOVED AND DISPOSED OF

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was DECANDIA WELL 8/21/00 FILE REASSIGNED

6/17/04 FILE REASSIGNED

NYSDEC FALL 1998 MTBE SURVEY INFORMATION FOR 9510367

Maximum MTBE concentration: 23000.0 PPB

Current MTBE concentration: 23000.0 PPB

BTEX offsite: No

Source of MTBE		Number of private drinking water wells impacted: 0
		Number of public water supply wells impacted: 0
Steel Underground Storage Tank	-	Number of private drinking water wells impacted: 0
Fiberglass Underground Tank	-	Number of replacement wells drilled: 0
Aboveground Storage Tank	-	Number of water main extensions: 0
Piping	-	Number of water main hookups: 0
Source not identified	- X	Number of residences provided w/ bottled water: 0
Other source	-	Number of people affected: 0

Indoor Air Impacts : No
Aquifer Impacts : Yes

Ongoing remediation: No

Monitoring Frequency
Monthly - Quarterly - X Semi-annual - Annual - Other -

Remedial Action used
No Action -

Groundwater		Soil	
Pump and Treat	-	Soil Vapor extraction	-
Air sparging	-	Excavation and disposal	- X
Bioreactor	-	Bioremediation	-
Natural attenuation	-	Low temp thermal desorption	-
Oxygen injection	-	Oxygen injection	-
Biosparging	-	Other	-
Dual phase extraction	-		
Other	-		

Under investigation: Yes
Dept. of Health involvement: No

Dept. of Health Remarks: No remarks given for this spill

General Remarks: BTEX off site unknown.