



HAZARDOUS MATERIAL SPILLS INFORMATION REQUEST

HENDERSON/MOBIL
RTE 9D/ KOSOVA LANE

FISHKILL, NY NO ZIP PROVIDED

Spill Number: 8501615

Close Date:

ADDRESS CHANGE INFORMATION

Revised street: 1432 RTE 9D
Revised zip code: 12590

Source of Spill: UNKNOWN
Notifier Type: Affected Persons
Caller Name:
DEC Investigator: MBMASTRO

Spiller: FERREIRA'S AUTOMOTIVE
Notifier Name:
Caller Agency:
Contact for more spill info:

Spiller Phone:
Notifier Phone:
Caller Phone:
Contact Person Phone:

Category: Known release which created a fire/explosion hazards (inside or outdoors), drinking water supply contamination, or significant releases to surface waters.
Class: Unable or Unwilling RP – DEC Field Response – DEC Corrective Action Required

Spill Date	Date Cleanup Ceased	Cause of Spill	Meets Cleanup Standards		Penalty Recommended	
08/08/1985		UNKNOWN	NO		YES	
Material Spilled	Material Class	Quantity Spilled	Units	Quantity Recovered	Units	Resource(s) Affected
UNKNOWN PETROLEUM	PETROLEUM	0.00	UNKNOWN	0.00	UNKNOWN	GROUNDWATER

Caller Remarks:

ONGOING PROBLEM-REPORTED TO DOT YEARS AGO-NO ACTION TAKEN SUBSURFACE INVESTIGATION UNDERWAY. VAPOR EXTRACTION SYSTEM AND PUMP & TREAT REMEDIATION SYSTEMS INSTALLED APRIL 93.

DEC Investigator Remarks:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was DECICCO 10/15/86 FILTERS TO BE INSTALLED; TANKS NEXT DOOR TO BE TESTED.

10/31/86 FILTERS INSTALLED; GAS STATION NEXT DOOR TESTING TANKS.

11/7/86 TANK TEST RESULTS INCONCLUSIVE DUE TO AIR IN SYSTEM

OWNER TO RETEST.

1/25/86 SAMPLES TAKEN PRE AND POST FILTER.

12/24/86 WELL PUMPED OUT NO PRODUCT SLIGHT SHEEN.

3/6/87

COMPLAINT FROM RESIDENT STAINING AND ODORS PROBLEM WITH
SULPHUR LAST SAMPLE RESULTS CLEAN.

3/23/87 FILTERS CHANGED.

03/29/88: THREE ADDITIONAL M.W. BEING INSTALLED, WELLS TO BE
SURVEYED & SAMPLED. GTI BELIEVES THAT MOBIL S/S ARE NOW
EXPERIENCING A PROBLEM. MAY NEED A PUMP TEST OF
HENDERSON'S WELL TO CHECK EFFECT OF M.W. K.WEED.

03/29/88: MONITORING WELLS CHECKED **ODOR OF GAS IN MW 3.**

06/14/88: FERREIRA TANKS TESTED TIGHT LINES TO REG TANK FAILED
AND WAS REMOVED NO SIGNIFICANT SPILLAGE.

08/19/88: GRDWATER TECH. ON SITE. GW TECH TO SAMPLE MW #4 AND AT
EDWARDS WELL.

10/18/88: CONTRACTOR AND D.E.C. ON SITE 9-20-88. CONTRACTOR TO
PROCEED BY DOING PUMP TEST OF HENDERSON W.W. ON OR
ABOUT 11-1-88.

10/01/97 LETTER SENT; ADVISING MR. FERREIRE THAT HE IS
RESPONSIBLE FOR SPILL;

12/10/15 Went to site with Todd, Aztech. Located 8 monitoring/recovery wells: MW-12, MW-13, MW-10, MW-3, RW-3, MW-7, MW-8 and
MW-9. **MW-3 had a sheen. MW-8 and MW-9 had free product. MW-10 had a strong petro odor.** MW-7 was dry and RW-3 was filled with
packer sand. Only sampled MW-12, MW-13, Mw-10 and MW-3...mm

1/27/16 Met with L Ferrara, the owner; E Cebel, the operator and potential buyer; P Dunn and M Carr, American Petroleum; D
Bendell, DEC. Mr Cebel **would like to buy the station but he does not want to be held responsible for the off site impacts at the
home adjacent to the station.** I emailed B Rigg, AG's office, to see if this is something they would be willing to discuss. L
Ferrara has agreed to hire American to vac out the 2 wells with product and resample the monitoring wells....mm

2-22-16, email from American, We performed the first vac event on Wells 8 and 9 last week. Vac is scheduled again this week. Based on gauging this week, we will make determination when all wells will be sampled. RDB

3-16-16 Met with Aztech. Continue quarterly GW sampling and POET O&M. Need to contact RP on ownership. GHP

7/14/16 After reviewing recent data, a letter has been sent to the RP asking for an investigation for an active remedial system...mm

2/14/17 – on February 14, Aztech met with DEC PMs to discuss the status of their PIN projects. Aztech to continue to maintain the POET. DEC to find out the status of the potential new gas station owner. KAB